

# Oil Field Environmental Incident Summary

**Incident:** 20140916162557      **Date/Time of Notice:** 09/16/2014 16:25

**Responsible Party:** C12 ENERGY: NORTH DAKOTA LLC

**Well Operator:** C12 ENERGY: NORTH DAKOTA LLC

**Well Name:** DICKINSON-HEATH-SAND UNIT 32

**Field Name:** DICKINSON

**Well File #:** 4332

**Date Incident:** 9/16/2014

**Time Incident:** 14:05

**Facility ID Number:**

**County:** STARK

**Twp:** 140

**Rng:** 96

**Sec:** 31

**Qtr:**

**Location Description:** Just 200' SW of the well location. Construction currently ongoing.

**Submitted By:** Owen Ryan

**Received By:**

**Contact Person:** Owen Ryan  
2054 UNIVERSITY AVENUE  
SUITE 400  
BERKELEY, CA 94794

**General Land Use:** Other - Described Above

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 700 Feet

**Distance Nearest Water Well:** 700 Feet

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	8	Barrels			8	barrels
Brine	8	Barrels			8	barrels

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 2/16/2015

**Clean Up Concluded:** 9/29/2014

**Risk Evaluation:**

No immediate risks.

**Areal Extent:**

**Potential Environmental Impacts:**

Impact is likely low. Construction company is moving around a lot of dirt and this dirt will be gathered up and removed. Spill was contained

**Action Taken or Planned:**

Wells were shut in to stop leak. Dirt is currently being cleaned up.

**Wastes Disposal Location:** Chimney Butte Landfill

**Agencies Involved:**

**Updates**

---

**Date:** 9/17/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a pipeline leak, remained on location according to the report. However, report wording indicates the leak actually occurred to the north of the location. Followup is necessary.

---

**Date:** 9/19/2014    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location at 9/19/2014.

Area is seeing significant work along a pipeline right of way. At the time of inspection, there was no sign of the reported spill.

No more followup is necessary.